JJEDI FOUR ARRIVAL (RNAV)

(JJEDI.JJEDI4) 27NOV25

HARTSFIELD/JACKSON ATLANTA INTL (ATL)

ATLANTA, GEORGIA

RNAV 1 - DME/DME/IRU or GPS.
RADAR required.

ATLANTA APP CON
134.725 379.9
D-ATIS ARR
119.65

ZELOW
YOUYU
JIRRI
PRMAN
SLVAA
004°
POOBA
Ldg ATL
(6)
004°
GRHAM
320°
(6)
DAFII
8000
320°
(9)
BBFET
11000 250K
CHWEE
11000 250K
FLKNN
14000 280K
JJEDI
10000 250K
(4)
(4)
8000
*2000
267°
(15)
14000
*2000
267°
(29)
LAYUH
267°
087°
15 NM
MELNM
14000
*2100
230°
(56)
SKWKR
14000
*2400
256°
(54)
EEWOK
14000
*2900
278°
(51)
099°
279°
15 NM
279°
LLNDO
280°
14000
*2000
280°
(32)
14000
*2000
280°
(48)
HOTHH
XWNNG
14000 280K
323°
*1900
(4)
8000
*2000
(15)
WOKIE
11000 250K
324°
*2000
(15)
8000
144°
15 NM
324°
DTSTR
14000 280K
14000
*2300
(29)
144°
15 NM
NEWHP
324°
14000
*2300
(17)
14000
*2300
287°
(56)
LARZZ
FL240
TYFTR
AADEN
165°
345°
15 NM
LAIRI
013°
193°
15 NM
N

NOTE: Jet aircraft only.
NOTE: Expect "descend via" clearance from Center; approach will assign landing runway.
NOTE: Select Rwy 27L.
NOTE: For use when landing west. When landing east, file and expect the SITTH (RNAV) ARRIVAL.
NOTE: MELNM transition, ATC assigned only.

(CONTINUED ON FOLLOWING PAGE)

NOTE: Chart not to scale.

(JJEDI.JJEDI4) 26190

JJEDI FOUR ARRIVAL (RNAV)

AL-26 (FAA)

HARTSFIELD/JACKSON ATLANTA INTL (ATL)

ATLANTA, GEORGIA

ARRIVAL ROUTE DESCRIPTION

EEWOK TRANSITION (EEWOK.JJEDI4)
HOTHH TRANSITION (HOTHH.JJEDI4)
LARZZ TRANSITION (LARZZ.JJEDI4)
LAYUH TRANSITION (LAYUH.JJEDI4)
MELNM TRANSITION (MELNM.JJEDI4)
SKWKR TRANSITION (SKWKR.JJEDI4)
TYFTR TRANSITION (TYFTR.JJEDI4)

From JJEDI on track 320° to cross DAFII at 8000, then on track 320° to GRHAM, then on track 004° to POOBA, then on track 004°. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS:

ASSIGNED RUNWAY 28 OR RUNWAY NOT ASSIGNED: Cross JJEDI at or above 10000; cross DAFII at 8000; cross POOBA at 5000; after POOBA descend to 3000 and proceed direct PRMAN; proceed on the ILS or RNAV RWY 28 approach.

ASSIGNED RUNWAY 27L: Cross JJEDI at or above 10000; cross DAFII at 8000; cross POOBA at 6000; after POOBA proceed direct SLVAA and proceed on the ILS or RNAV RWY 27L approach.

ASSIGNED RUNWAY 27R: Cross JJEDI at or above 10000; cross DAFII at 8000; cross POOBA at 6000; after POOBA proceed direct YOUYU and proceed on the ILS or RNAV RWY 27R approach.

ASSIGNED RUNWAY 26L: Cross JJEDI at or above 10000; cross DAFII at 8000; cross POOBA at 6000; after POOBA proceed direct JIRRI and proceed on the ILS or RNAV RWY 26L approach.

ASSIGNED RUNWAY 26R: Cross JJEDI at or above 10000; cross DAFII at 8000; cross POOBA at 6000; after POOBA proceed direct ZELOW and proceed on the ILS or RNAV RWY 26R approach.

SE-4, 29 OCT 2026 to 26 NOV 2026