


ILS RWY 4 (CAT II & III)
GREENVILLE SPARTANBURG INTL (GSP)

**T
A**

ALSF-2



MISSED APPROACH:
Climb to 3000 then
right turn direct SPA
VORTAC and hold.



CATEGORY	A	B	C	D
S-ILS 4	CAT II RA	142/12	100 DA	1047
S-ILS 4		CAT IIIa	RVR 07	
S-ILS 4		CAT IIIb	RVR 06	
S-ILS 4		CAT IIIc	NA	

CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

