



HI-ILS Y or LOC Y RWY 10

LOC I-MGM 109.9	APCH CRS 097°	Rwy Ldg TDZE Arpt Elev 9020 219 232	[USAF]	MONTGOMERY RGNL (DANNELLY FLD) (KMGM)
DME required. ADF and DME required for LOC only.				MISSED APPROACH: Climb to 700 then climbing right turn to 3000 Direct MGM VORTAC and hold, continue climb in hold to 3000. TACAN aircraft continue to 3500 on MGM R-126 to SHADY/ MGM 15 DME and hold southeast, right turn, 306° inbound.
V * When ALS inop, increase RVR to 40 vis to 3 1/4 miles. ** When ALS inop, increase vis to 1 3/4 miles. A *** Circling not authorized for CAT E, N of Rwy 10-28.				

ATIS 120.675	APP CON ★ 124.0 363.025	DANNELLY TOWER ★ 119.7(CTAF) 0 360.85	GND CON 121.7 348.6	CLNC DEL 118.3 270.3	UNICOM 112.95
-----------------	----------------------------	--	------------------------	-------------------------	------------------



EMERG SAFE ALT 100 NM 5000



MONTGOMERY, ALABAMA

32°18'N-86°24'W

MONTGOMERY RGNL (DANNELLY FLD) (KMGM)

Amdt 9E 23JAN25

HI-ILS Y or LOC Y RWY 10